JUNE


2019

artisJet

Customer Care & Training

proV6

A5 LED UV PRINTER



ARTISJET WORK STATION V1.0

CONFIGURATION & WORKING SECTIONS

ABOUT THIS FILE

The **DIGITAL SMART PRINT WORKSTATION** from **artisJet proV6 A5 LED UV Printer** improves productivity by multiples task printing at **ONE CLICK.**.

This manual introduces the easy-to-follow working sections of artisJet Work Station for artisJet proV6 A5 LED UV printer model.

Contents

OVERVIEW..... 4

FUNCTIONS..... 5

SETTINGS..... 6

PM..... 7

PRINTING PROCESS..... 8


JOB QUEUES..... 9

JOB QUEUES SET 1..... 10

JOB QUEUES SET 2..... 11

PRINTED LIST..... 12

GET TO KNOW THE INTERFACE



Copyright © 2019 Signs Full Joint Tech Co.,Ltd

FUNCTIONS

WHAT DOES EACH FUNCTION DO?

Functions	Characteristics
	Create a new PRN task / Open the RIP; Single Click → Start to work in the back end; Double Click → Start to create and edit new jobs.
	Import a ready PRN job
	Save the PRN jobs / files to any location on demand
	Start the print
	Cancel the printing job in progress
	Delete the PRN file from the work station
	Click to access the settings features
	Printer Maintenance

Copyright © 2019 Signs Full Joint Tech Co.,Ltd

SETTING FUNCTION


ACCESSING THE SETTINGS

If save the file or not, after printing

Delete printed files
Save to Complete Task List

Feathering options (S=small, M=Middle; F=Full)

S Feather
M Feather
F Feather



If the printed job still to be listed in the Job Queues

Delete from Task List
Keep it in the Task List

UV Light Directions (Unidirection, Bidirection)

Uniderection
Biderection

Save the Settings

Exit the Settings


Copyright © 2019 Signs Full Joint Tech Co.,Ltd

PM FUNCTION



PRINTER MAINTENANCE






Click to print the nozzle check

Exit the tab

Copyright © 2019 Signs Full Joint Tech Co.,Ltd

PRINTING PROGRESS

TASKS IN PROGRESS AREA



Print job status

Print size

Print task progress

Printing progress

#	State	Job Title	Size	Copies	progress	3D Embossed
1	Connect failed	C:\MTOutput\2019-06-21- 0\1.prn	4.3306" x 2.2042"	1	0%	N/A

PRN location & name


Copies to print on this job


Embossed options selected

Copyright © 2019 Signs Full Joint Tech Co.,Ltd

JOB QUEUES

PENDING TASKS






Copyright © 2019 Signs Full Joint Tech Co.,Ltd

JOB QUEUE SET 1


RIGHT CLICK ON THE JOB QUEUES




Copyright © 2019 Signs Full Joint Tech Co.,Ltd

JOB QUEUE SET 2


ENTER THE JOB PRINTING SET




Define the job copies




Select the embossed effect mode






Select the feathering options




Copyright © 2019 Signs Full Joint Tech Co.,Ltd

PRINTED LIST

RIGHT CLICK ON THE JOB QUEUES





Copyright © 2019 Signs Full Joint Tech Co.,Ltd

CONNECT WITH US

YouTube/artisJet

Facebook/artisJetSolutions

Instagram/artisjet

Twitter/artisJet

Pinterest/artisjet

Flickr/artisJet

artisjet.com | info@artisjet.com | +86 158 1111 9658